

# Product Information

November 2008  
Aftersales/Accessories/Drive train/Tuning Kits  
Pl: SZ\_004\_01\_08



## JOHN COOPER WORKS TUNING

### 17" sports brake with sports brake disc perforated and grooved

**R55 (except R55 JOHN COOPER WORKS CLUBMAN)**

**R56 (except R56 JOHN COOPER WORKS)**

**R57 (except R57 JOHN COOPER WORKS CONVERTIBLE)**

### Accessories

Management

Marketing

Sales of new Cars

Sales of used Cars

Aftersales

Administration

#### Product description

The 17" sports brake is similar to the standard brakes of the R55 JOHN COOPER WORKS CLUBMAN/R56 JOHN COOPER WORKS/R57 JOHN COOPER WORKS CONVERTIBLE, except that the front discs are additionally perforated and grooved.

- 4-piston aluminium fixed calliper on the front axle finished in red including JOHN COOPER WORKS logo.
- Perforated and grooved, internally ventilated brake discs on the front axle.
- Red-painted single-piston fixed calliper on the rear axle.
- Solid brake discs on the rear axle.
- Not available ex-works.



17" JCW sport brake with perforated and grooved sport brake disc

#### Sales features/benefits

- The 17" JOHN COOPER WORKS sport brake for the MINI improves thermal capacity due to larger, internally ventilated brake discs.
- The perforations and grooves in the JOHN COOPER WORKS front axle sport brake discs reduce formation of a film of water between the brake pad and the brake disc.
- Attractive design.
- Underlines the sporty character, particularly when combined with open-spoke alloy wheels.

#### Homologation

The JOHN COOPER WORKS sport brake is included in EG-BE No. e1\*2001/116\*0343\*08 (R55, R56, R57).

Despite this, a national homologation and the changing of the vehicle documentation is always necessary, as the brake system differs in the data relevant to the approval (see also TÜV Test Report No. 07-01096-CP-GBM-00).

#### Availability

from 03/2008

#### Installation time

approx. 3.5 hours

#### EPC DVD

from 03/2008

#### Installation instructions

see ISTA

#### Part number

17" JCW sport brake

34 11 0 432 802

(continued on page 2)